



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

11-16-87

File Jph SU

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: November 4, 1987
11:00 AM to 1:00 PM

Permittee and/or Operators Name: Genwal Coal Company
Business Address: P.O. Box 1201, Huntington, Utah 84527
Mine Name: Crandall Canyon Permit Number: ACT/015/032
Type of Mining Activity: Underground ☒ Surface ☐ Other ☐
County: Emery
Company Official (s): Andy King, office and Lannie Burnside, on-site
State Official(s): James Leatherwood
Partial: XX Complete: Date of Last Inspection: October 21, 1987
Weather Conditions: sunny and cool
Acreage: Permitted 164.4 Disturbed 5.15 Regraded 0.5 Seeded 0.5 Bonded 5.15
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	(X)
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION: 11/04/87

(Comments are Numbered to Correspond with Topics Listed Above)

2. Signs and Markers. Buffer zone signs have been installed at each topsoil stockpile, between the stockpile and Crandall Creek. These signs adequately identify the buffer zone at each topsoil stockpile.

4.d. Other Sediment Control Measures. The straw berms located near the inlet to diversion C-2 have filtered out sediment from the diversion. I explained to Mr. Burnside that the soil must be removed to maintain a functional berm. Mr. Burnside said he would clean it out immediately. The straw berm was functional at the time of inspection.

4.f. Effluent Limitations. No discharge was occurring at the approved NPDES discharge point at the time of this inspection. Mr. King stated that there has been no discharge for the fourth quarter to date.

Copy of this Report:

Mailed to: Mr. Charles Gent - Genwal Coal Co., Donna Griffin - OSM

Given to: Joe Helfrich - DOGM

Inspectors Signature and Number: *Joe Helfrich* #16 Date: 11/9/87